Morgan County Engineer's Office


Stevan Hook, P.E., P.S.



Presented by


Stevan Hook, P.E., P.S. County Engineer

McConnelsville, Ohio





McConnelsville, Ohio



McConnelsville, Ohio

• Rural – 421 Square Miles



McConnelsville, Ohio

- Rural 421 Square Miles
- Population: County 14,827




McConnelsville, Ohio

- Rural 421 Square Miles
- Population: County 14,827
- 344 Miles of County Roads
- 365 Miles of Township Roads



McConnelsville, Ohio

- Rural 421 Square Miles
- Population: County 14,827
- 344 Miles of County Roads
- 365 Miles of Township Roads
- 203 bridges & 448 culverts




45,000 ft 13,500 m

Morgan County, OH; Bruce Harris & Associates

McConnelsville, Ohio

- Rural 421 Square Miles
- Population: County 14,827
- 344 Miles of County Roads
- 365 Miles of Township Roads
- 203 bridges & 448 culverts
- Elevation Difference 552ft.
- 1168 elev. to 516 elev.




13.500 m

Morgan County, OH; Bruce Harris & Associates

McConnelsville, Ohio

- Rural 421 Square Miles
- Population: County 14,827
- 344 Miles of County Roads
- 365 Miles of Township Roads
- 204 bridges & 448 culverts
- Elevation Difference 552ft.
- 1168 elev. to 516 elev.
- Budget: \$3.28 Million



13.500 m

McConnelsville, Ohio

Making our bridge dollars go further,

McConnelsville, Ohio

McConnelsville, Ohio

Making our bridge dollars go further, and extend the life of our bridges

• 11 – New bridges

McConnelsville, Ohio

- 11 New bridges
- 42 rehabbed bridges

McConnelsville, Ohio

- 11 New bridges
- 42 rehabbed bridges
- 7 Used Railroad Tanker Cars

McConnelsville, Ohio

- 11 New bridges
- 42 rehabbed bridges
- 7 Used Railroad Tanker Cars
- 2 GRS Abutment Projects

McConnelsville, Ohio

- 11 New bridges
- 42 rehabbed bridges
- 7 Used Railroad Tanker Cars
- 2 GRS Abutment Projects
- Used Steel

McConnelsville, Ohio

- 11 New bridges
- 42 rehabbed bridges
- 7 Used Railroad Tanker Cars
- 2 GRS Abutment Projects
- Used Steel
- Wash lose materials from steel

McConnelsville, Ohio

- 11 New bridges
- 42 rehabbed bridges
- 7 Used Railroad Tanker Cars
- 2 GRS abutment Projects
- Used Steel
- Wash lose materials from steel
- Rip/rap for scour protection

 Used to replace short bridges & box culverts. – This is a special niche situation.

- Used to replace short bridges & box culverts. – This is a special niche situation.
- Relatively easy & quick to install.

- Used to replace short bridges & box culverts. – This is a special niche situation.
- Relatively easy & quick to install.
- Headwall is for washout protection.

- Used to replace short bridges & box culverts. – This is a special niche situation.
- Relatively easy & quick to install.
- Headwall is for washout protection.
- Job was completed in 2008.

- Used to replace short bridges & box culverts. – This is a special niche situation.
- Relatively easy & quick to install.
- Headwall is for washout protection.
- Job was completed in 2008.
- How long? -7 days.

- Used to replace short bridges & box culverts. – This is a special niche situation.
- Relatively easy & quick to install.
- Headwall is for washout protection.
- Job was completed in 2008.
- How long? -7 days.
- Cost? \$25,700.

- Used to replace short bridges & box culverts. – This is a special niche situation.
- Relatively easy & quick to install.
- Headwall is for washout protection.
- Job was completed in 2008.
- How long? -7 days.
- Cost? \$20,700.
- Problems? Getting pipe to site location

Tanker cars laying in the yard



Before in 2009



The barrow area was used to fill over pipe & create sight distance.



Downstream headwall is 12" thick and 3' below bottom of pipe.



Upstream is the same but wider for erosion protection.




Finished project



Old concrete abutments were utilized as rock slope protection.



How it looks 9 years later



What not to do!! -with acid water



This will have to be replaced, not sure with what!!!



GRS - Abutment Replacement

View prior to abutment failure due to scour. 5,000 acre drainage & on an outside bend of creek.



GRS Abutment Repair

Completed in the fall of 2008



We raised bridge above old abutment & anchored back



Poured footer to get a level surface, would not do this next time. Would just use a compacted stone base & lay block directly on it.



First course of block and fabric



At the 4th tier



At the 10th tier



After Completion in November 2008



After Completion in November 2008



After Completion in November 2008



Topside view & finish work



April 2009 – Following spring



April 2017 - Wall still straight



Typical Design



 CALCULATION SHEET

 JOB NO.112044-31 SHEET NO. 2
 0F29


 BRIDGE NO.
 #340 - CR 58

 CALCULATED BY
 ALP
 DATE
 11/8/12

BRIDGE #340 - CR 58

SFN 5837340

YEAR BUILT: 1951



TRANSVERSE SECTION



 CALCULATION SHEET


 JOB NO. 112044-31 SHEET NO. 4 OF 29

 BRIDGE NO. 540 CR 58
 #340 - CR 58

 CALCULATED BY ALP DATE 11/8/12

BRIDGE #340 - CR 58

SFN 5837340



FRAMING PLAN

• We have 30 bridges of this design.

- We have 30 bridges of this design.
- Were built after the war 40's & 50's, were easy and cheap, & as late as 2001

- We have 30 bridges of this design.
- Were built after the war 40's & 50's, were easy and cheap, & as late as 2001.
- Girders control on only two bridges, it is the stringers that are the weak point.

- We have 30 bridges of this design.
- Were built after the war 40's & 50's, were easy and cheap, & as late as 2001.
- Girders control on only two of the bridges, it is the stringers that are the weak point.
- With our deck design we have made that problem worse.

Bridge has a load limit due to stringer section loss at the girders.



Sun light shining thru gap.




Here is the result.




Section loss in web
 of stringer as a
 result of,

This is the controlling condition for the load rating problems.



- Section loss in web of stringer as a result of,
- Material build-up on bottom girder flange.

Here is the main load rating problem & cause.



- Section loss in web of stringer
- Material build-up on bottom girder flange.
- Began a bridge washing program to buy time.

Access to work area under the bridge was a big problem. This was the bridge crew's solution.



Plating added to the web and bottom flange to improve shear strength.



Plating added to the web and bottom flange to improve shear strength. However this is just a Band-Aid; until the bridge can replaced in 2023.



Questions?

